


USED VEHICLE INSPECTION REPORT







ADESA Charlotte
11600 Fruehauf Drive
Charlotte, NC 28273
Phone: (704) 587-7653
Fax: (704) 504-1941

Company
Name: M&T BANK
Client Unit ID: 11080025040001
Lessee/Borrower:
Stock Number: 531150
Lot Location:
Rental Account:

Customer
Number: CF492
Cat Code:
Vehicle Type:
Arrival Date: 01/06/2012 12:00 AM
License:
License State:

VIN				Year	Make Body Style		Model Trim		Series Or Truck Dsc		Doors #P	Lift Gate										
5	N	H	U	A	M	H	3	8	7	U	3	2	4	1	5	5	07	CONTINENTAL CAR	TRALIER		2	N
																				0		
Mileage	Odo	Type	Fuel	DT	Transmission			Engine			Exterior Color		Int Color / Type		Wheel	Base	Mats					
					N	Automatic						White / Code:	Grey / Code:									N
Sound				Roof					 			Equipment: Engine Details:2 Cylinder Gas, Roof Type:Hard Top, Tire Brand:radial, Transmission Type:Automatic, Wheel Diameter:15 inches, Wheel Type:Steel										
				Hard Top																		



Keys
 Ignition Code Trunk Alarm
 Master: Valet: Mobilizer: Wallet:
 Seating Configuration:

Total Chargeable Damage: _____				Total Non-Chargeable Damage: _____										
Damage Desc.			Damage Action	Y D	T D	S A	Airbrush Amount	Body Hours	Ref Hours	Labor Amount	Parts	PDR Amount	Total Charges	C/ NC
Totals							0.00	0.00	0.00	0.00	0.00	0.00	0.00	

YD = Yard Damage TD = Transport Damage SA = Suggested Action

Pickup Date:
 Return Date:
 Acceptance Date:
 Reject Codes:

Mileage of Last Service:
 Last Service Date:
 Mechanical Rating:
 General Condition: Average

Certification Candidate:

Appraisal Required:

File Claim:

Request Previous RO:

Deductible Amount: \$0.00
De-Identify:

Internet Candidate:
 Interior Condition: Average
 Drivable: Y

Condition: Grade 3-Average


Statements:

Comments: TOW 15600LBS
 WIRE BROKEN ON FOLD DOWN REAR DOOR
 SPOT FOR GENERATOR (GENERATOR MISSING)
 LIGHTS ELECTRICAL OUTLETS AND CABINETS ON INSIDE
 HAS AWNING AND IS TORN

Recondition Instructions: Complete Detail

Body Shop Total:	0.00
B/S Parts Total:	0.00
PDR Total:	0.00
Glass Total:	0.00
Tires Total:	0.00
Mechanical Total:	0.00
Recon Total:	0.00
Misc:	0.00
Total:	0.00





Title Received: 02/13/2012

Account Signature: _____

Detail Fees Not Included

Acceptance Date: _____

Date: 02/27/2012

Inspection Report Prepared by: Corey Pannell

Date: 01/19/2012 03:44:31 PM